



FLI Environmental

69 BRIDGE STREET
DEDHAM, MA 02026

(781) 251-0040

Invoice

Date	Invoice #
12/30/2022	39849

Bill To:

Town of Hingham
Accounts Payable
210 Central St.
Hingham, MA 02043

Service Address:

29-31 Rhodes Circle
Hingham, MA 02043

Rep	Customer Contact	FLI Job #	Purchase Order Number
DAM		22-2684	

Quantity	Unit	Item	Description	Rate	Amount
1	LS	Final Vis...	Final Visual Clearance	395.00	395.00

It's been a pleasure working with you!	www.flienv.com	Payments/Credits	\$0.00
	jmckie@flienv.com		Total Due
	Federal Tax ID # 04-3245544		

Subject to a 1.5% monthly finance charge if not paid in full within 30 days. Credit cards accepted.

Payment Due Upon Receipt

December 29, 2022

Client: Town of Hingham
Contractor: Banner Environmental
FLI Project #: 22-2684
Site Location: 29-31 Rhodes Circle
Hingham, MA

Dear Sir/Madam:

FLI Environmental, Inc. (FLI) conducted a post-abatement final visual inspection after asbestos removal at the above referenced location. The identified asbestos materials were abated according to applicable state and federal regulations. The visual inspection was completed by FLI's state licensed and EPA accredited Asbestos Project Monitor listed below:

Project Monitor: Rebecca Dittami
License #: AM900708

The work area passed the clearance criteria. Project details are included on the attached Final Visual Clearance Inspection Checklist.

Should you have any questions regarding this letter or project, please do not hesitate to contact us at (781) 251-0040. FLI appreciates the opportunity to provide you with our services.

Sincerely,
FLI Environmental, Inc.



Steve Shea
Manager, Field Services



Final Visual Clearance Inspection Checklist

Client: Town of Hingham

Asbestos Contractor: Banner Environmental

Date: December 29, 2022

Job Site: 29-31 Rhodes Circle

Work Area: Garage

Project #: 22-2684

Hingham, MA

Decon Type: N/A

Time: 11:30

Material	Quantity
Pipe Insulation	24 LF

Pass

Fail

Certification

The undersigned verify the materials listed have been removed and the work area outlined above has been inspected and has passed the visual inspection criteria of no visible debris.

Name

Signature

License #

Project Monitor: Rebecca Dittami

AM900708

Supervisor: Sandro Loja

AS901083

Additional Notes:

MA Lab License AA000144 - RI Lab License AAL-098